












**TORNILLO**

- ①   $\phi 3.5 \times 70$  18Pcs
- ②   $\phi 3.5 \times 60$  31Pcs
- ③   $\phi 3.5 \times 35$  19Pcs
- ④   $\phi 3.5 \times 25$  29Pcs
- ⑤   $\phi 3 \times 20$  7Pcs


**TORNILLOS Y TUERCAS**

- ⑥   $M6 \times 55$  4Pcs
- ⑦   $M6 \times 65$  4Pcs




A 	B 	C 	D 	E 	F x 4 
G 	H 	I 	J 	K x 3 	L x 2 
M 	N 	O 	P 	Q 	R 
S 	T x 2 	U x 2 	V x 2 	W x 4 	

**PASO-1**




- ①   $\phi 3.5 \times 70$  5Pcs
- ②   $\phi 3.5 \times 60$  6Pcs

**PASO-2**




- ①   $\phi 3.5 \times 70$  6Pcs
- ②   $\phi 3.5 \times 60$  6Pcs

**PASO-3**




- ①   $\phi 3.5 \times 60$  12Pcs
- ⑥  M6x55 4Pcs

**PASO-4**




- ①   $\phi 3.5 \times 70$  6Pcs


**PASO-5**



**PASO-6**



**PASO-7**



**PASO-8**

